Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080141-7

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

2961 E. COLORADO ST., PASADENA, CALIF.

No. 11414

RECEIVED FROM PLANT #9

DATE REC'D. 2-27-57

P.O. NO.

VENDOR PACKING SLIP NO.

CHARGE TO	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	O R	ACCT. OR W.O. NO. / S.O. NO.
	322	0	10	0	20					

QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION	QUANTITY ACCEPTED	QUANTITY REJECTED	REMARKS
2	731266 Bearing Bracket Assembly IP3 #A003341	2		

RECEIVED BY [signature] HMC-1083

INSPECTED BY [signature] DATE 3/1/57

REJECTS RETURNED ON SHIP. MEMO NO.

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

2961 E. COLORADO ST., PASADENA, CALIF.

No. 11417

RECEIVED FROM PLANT #9

DATE REC'D. 2-27-57

P.O. NO.

VENDOR PACKING SLIP NO.

CHARGE TO	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	O R	ACCT. OR W.O. NO. / S.O. NO.
	322	0	9	0	20					

QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION	QUANTITY ACCEPTED	QUANTITY REJECTED	REMARKS
24	731298 Bracket Assembly Switch Adjust IP3 #A003335	24		

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080141-7

RECEIVED BY [signature]

INSPECTED BY [signature] DATE 3/2/57

REJECTS RETURNED ON SHIP. MEMO NO.